

 DURING BACKFILL CARE SHOULD BE TAKEN NOT TO DAMAGE TRACER WIRE INSULATION.

DRAWN BY: TCS CHECKED BY: GB

N.T.S. SCALE:

09/12/25 DATE:

TRACER WIRE TEST STATION

